

#### Daily Activity Report TILCON TCRA 03032011 (UNCLASSIFIED)

Friday, March 4, 2011 9:48 AM

From: "Gabel, Ted Mr CIV USA IMCOM" < ted.gabel@us.army.mil>

To: "Greg Zalaskus" <Greg.Zalaskus@dep.state.nj.us>, Roach.Bill@epamail.epa.gov, "Joe Marchesani" <Joe.Marchesani@dep.state.nj.us>, "B Dolce" <subsurfacesolns@earthlink.net>, "Michael Glaab" <michaelglaab@worldnet.att.net>, "Jim Kealy" <Jim.Kealy@dep.state.nj.us>, "Jim Pastorick"



1 File (697KB)

<uxopro@gmail.com>



03032011 T

Classification: UNCLASSIFIED

Caveats: NONE

All:

Daily Activity Report from yesterday for your files. Detonation of the items found is today - as we heard in the meeting last night.

Ted Gabel Project Manager for Environmental Restoration US Army Garrison, Picatinny Arsenal INCOM-NERO-PIC-PWE B319

Picatinny Arsenal, NJ 07806-5000 Commercial: (973) 724-6748

Fax: (973)-724-5398 DSN: (312) 880-6748

"We are the Army's Home in Northern New Jersey"

Classification: UNCLASSIFIED

Caveats: NONE



### DAILY REPORT

Daily Activities for: 03-03-2011	
Weather: 14-32 degrees clear very cold du	e to winds
Personnel on-site:	
Steven Burhans - Senior UXO Supervisor	
Don Giouard – UXO Site Safety/QC	Marty Holmes - USACE Baltimore
Tim Jones - UXO Tech III	
Callie Phillips - UXO Tech II	
Lonnie Cuny - UXO Tech II	
David Sherer - UXO Tech II	
Mitchell Price - UXO Tech I	
Preston Lindbeck - UXO Tech I	
Tyler Szelig - UXO Tech I	

### **Summary of Activities:**

**Mag and Flag Operations:** Complete.

• Intrusive Operations: Complete

**QC/QA:** Complete

**Prep for Demo:** 

• Check Firing wire and related electrical equipment.

### **Equipment clean up and storage:**

Valons disassembled and cleaned. Equipment sorted for storage and shipping.

Work Completed:	Today	Cumulative
Number of Anomalies flagged	0	898
Number of Anomalies investigated	0	1022
Number of Grids QA/QC	0	12
Number of grids completed	0	12



	Materials R	Recovered during today's Operations	
	Quantity	Location/Grid	Disposition
MEC	-	-	-
MD	-	-	-
Non-MD Scrap	-	-	-

**Health and Safety:** All personnel on site have read Work Plan and HASP. Tailgate safety meeting held by Team leader and team.

#### **Quality Control:**

Inspections Performed	Non- Conformances	Corrective Action (CA)	Follow-up on CA
Vallon/Schonstedt	None		
All metals detectors(White)	None		
Vehicle Inspections	None		

Notes: Today 25.42tons of additional play ground quality sand was delivered to the demo site. Total sand is 75 Tons on hand. 948 issued for clearance of work area (see attached form below).

### **Upcoming Activities:**

- Equipment Turn in
- MD Turn in
- Demolitions Operations

**SUXOS:** Steve Burhans (443-804-7448) **UXO SS/QC:** Don Giouard (281-667-5061)



#### PHOTO DOCUMENTATION



## **USACE OESS review of Demo location TILCON 03032011**





75 Tons of Sand for DEMO procedures Tilcon 03032011





24 inch base of sand for Demo site Tilcon 03032011



MEC Qty	MEC Found - Nomenclature	X	Y	Z	Date Located	Date Destroyed	QC Pass Date	Comments
1	MK 20 6 inch	-	-	-	030211			GPS location documented
1	6 inch Low ordered	-	-	-	030211			GPS location documented
1	MK 10 Fuze	-	-	-	030211			GPS location documented
1	MK 10 Fuze	-	-	-	030211			GPS location documented
	Qty 1 1 1	QtyNomenclature1MK 20 6 inch16 inch Low ordered1MK 10 Fuze	QtyNomenclature1MK 20 6 inch-16 inch Low ordered-1MK 10 Fuze-	Qty         Nomenclature           1         MK 20 6 inch         -         -           1         6 inch Low ordered         -         -           1         MK 10 Fuze         -         -	Qty         Nomenclature           1         MK 20 6 inch         -         -         -           1         6 inch Low ordered         -         -         -           1         MK 10 Fuze         -         -         -	Qty         Nomenclature         Located           1         MK 20 6 inch         -         -         -         030211           1         6 inch Low ordered         -         -         030211           1         MK 10 Fuze         -         -         030211	Qty         Nomenclature         Located         Destroyed           1         MK 20 6 inch         -         -         -         030211           1         6 inch Low ordered         -         -         -         030211           1         MK 10 Fuze         -         -         030211	Qty         Nomenclature         Located         Destroyed         Pass Date           1         MK 20 6 inch         -         -         030211           1         6 inch Low ordered         -         -         030211           1         MK 10 Fuze         -         -         030211



# **Demo Shot Log**

Date	Grid	MEC	UXO	Status	#	Demo	Demo	Shot	Shot
	No.	Qty	Nomenclature		Deliveries	Consumed	Qty	Cleared (Y/N)	Record



Ordnance	of Engineers Baltimo e and Explosives Safe Memo	re District ty
TO: ARCADIS/PIKA	<b>DATE</b> : 02 Mar 2011	TIME: 1500
Contract Number: W912DR-09-C-0086 DOCUMENT #: 1	Project Location: Tilcon Quarry	
SUBJECT ITEMS (C Work Plan Safety Violation	CHECK ALL THAT APP  X Quality Assuran  Other	
Safety Comments		
		and D-32
<b>DESCRIPTION</b> : The following grid C-37, D-37, C-36, D-36, C-35, D-35, C-36	e with contract specification	and D-32
<b>DESCRIPTION</b> : The following grid C-37, D-37, C-36, D-36, C-35, D-35, C-36	e with contract specification  What is the specification of the specific	ons is requested  Representative AB OE Safety Specialis
DESCRIPTION: The following grid C-37, D-37, C-36, D-36, C-35, D-35, C-3	e with contract specification  What is the specification of the specific	ons is requested  Representative B OE Safety Specialis